
WO 2005/031010 PCT/GB2004/004145






Fig. 2

2/5




Figure 3





Figure 4



TYPICAL PRECIOUS METAL RECOVERY PLANT

Fig. 5 Rapid Leaching of Metals

WO 2005/031010 PCT/GB2004/004145

5/5




Fig. 6